



Consolidated Edison Company
of New York, Inc.
4 Irving Place
New York NY 10003
www.conEd.com

April 12, 2010

To: All Licensed Plumbers in the Con Edison Service Territory

We are notifying you of a product recall by Fisher of their product S302, the 1-inch X 1¼-inch (inlet/outlet) regulator with identification label "HFF" Con Edison nomenclature. It is being recalled because the orifice is incorrectly sized thereby possibly compromising the equipment life.

The HFF regulators have a metal badge with a Con Edison serial number of "HFF - 440016" through "HFF - 440315" located on top of the regulator body. Additionally, the manufacturer's badge for this regulator is marked with OR. ½-inch (orifice = ½-inch) and date of XX-08 (month/year). These regulators are normally installed at small commercial customers with Class 500, 1000, and 3000 meters.

If an HFF regulator is found with the identifiers and serial numbers, please call Nick Luberto at (646) 739-2531 or Greg Ludwig at (646) 235-7043 for immediate disposition of the regulators.

To view the regulator, please go to:

<http://ceintranet/sites/GasOps/GasEHS/Safety%20and%20Environmental%20Alerts/2010-No.006%20Fisher%20Recall.pdf> or view the attached Pdf.

You cooperation is greatly appreciated.

Sincerely,

Anita Ma
General Manager
Energy Services